

INDI S52- LOZ 90 (KAPKAC)

Diagram showing the exploded view of the bed frame components: 1 (side rails), 2 (headboard/footboard), 3 (cross slats), and 4 (end rails).

Table 1:

A	B	C	D	
1	S52-130	2000	260	1/2
2	S52-025	974	795	2/2
3	S52-131	910	200	1/2
4	S52-026	974	495	2/2

Table 2:

32x	1x	4x	4x	4x	4x	4x
FE.3x16 mm e7	z1	n63	k1	40x13 mm r5'	Micro mm r5'	s1
1x	8x					
15g y1'	Ø6x30mm f1					

Icons: Safety symbols (S1, S2), person icons, and tool icons (screwdriver, hammer, level).

1/4

S52- LOZ 90

1

Diagram showing the assembly of the side rails (1) to the end rails (4) and headboard/footboard (2). Includes a warning symbol **S2** and a note: "f1 must be inserted into the hole".

Diagram showing the attachment of cross slats (3) to the side rails (1) using screws (f1).

Diagram showing the attachment of the headboard/footboard (2) to the end rails (4) using brackets (k1).

2/4

S52- LOZ 90

2

Diagram showing the attachment of the headboard/footboard (2) to the side rails (1) using brackets (k1). Includes warning symbols **S6** and **S21**.

Diagram showing the attachment of the cross slats (3) to the side rails (1) using screws (s1).

3

Diagram showing the final assembly of the bed frame, including the attachment of the headboard/footboard (2) to the side rails (1) using brackets (k1).

Diagram showing the attachment of the cross slats (3) to the side rails (1) using screws (s1).

3/4

S52- LOZ 90

4/4

